

Title: Dry dock brokerage and attending at Yiulian (SK) shipyard

Period: Feb 2016

Vessel: Chemical Tanker

2nd Special Survey

Dock repair commenced just after Chinese Lunar Year, Many yard workers still enjoy their lives in home town. It is lucky that this vessel no happened any delay and finished on schedule.

(Picture: Finished 2nd T/U coating in No.4 Dry dock)



We attended all repair job from enter dry-dock (dock master onboard) to sea trial.

All the repair job smoothly finished with owner, and shipyard effort.

(Picture: Taken from tug boat and say bye-bye to vessel)



Kunimori Shanghai Staff who attended this time:

He has experience of repair manager in one famous Chinese shipyard.

He attended all repair progress of this vessel and attained good evaluation from Ship Owner.

Picture: Before undocking and after checking bottom condition.